Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

847 PRIVATE RESIDENCE NY Spills \$108764420 NNW 2070 WEST 12TH ST N/A

> 1 1.155 mi. 6097 ft. BROOKLYN, NY

 Relative:
 SPILLS:

 Higher
 Name:
 PRIVATE RESIDENCE

 Actual:
 Address:
 2070 WEST 12TH ST

 13 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0706489 / 2007-10-15

 Facility ID:
 0706489

 Facility Type:
 ER

 DER Facility ID:
 336425

 Site ID:
 387015

 DEC Region:
 2

Spill Cause: Equipment Failure

 Spill Class:
 C4

 SWIS:
 2401

 Spill Date:
 2007-09-10

 Investigator:
 rmpiper

 Referred To:
 Not reported

 Reported to Dept:
 2007-09-10

 CID:
 27

Water Affected: Not reported Private Dwelling Spill Source: Spill Notifier: Local Agency Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: 0

Date Entered In Computer: 2007-09-11
Spill Record Last Update: 2007-10-15
Spiller Name: SI-KAL

Spiller Company: PRIVATE RESIDENCE
Spiller Address: 2070 WEST 12TH ST

Spiller Company: 001 Contact Name: SI-KAL

DEC Memo: "DEC Piper placed call into ptero req spill info. 10-1-07- CSL sent to as per property shark Ting Kwei Sze 2070 W. 12th Street Brookyln,

NY 11223 PW Grosser was contacted to provide cost estimate. 10/15/07-DEC Piper visited site. Inspection of residence revealed no odors. PID readings were at backround levels. Piper placed unit near hole where feed line entered flooring. Slight elevation at 8ppm as opposed to background at 3ppm. The last delivery was in March 2007. Line passed on 4/20/07. Gauge on tank was not working and may be reason why PEtro thought line leak. A delivery of 230 gal was made on 9/11

to fill tank. Sludge may havve clogged line. No further action

granted. Closed."

Remarks: "Caller reports a leak in the oil line between the tank and the

furnace. Spill is in the basement of the home. Spill onto cement

floor. Unk who will be doing the cleanup at this time."

All Materials:

 Site ID:
 387015

 Operable Unit ID:
 1144238

 Operable Unit:
 01

 Material ID:
 2134535

Map ID MAP FINDINGS
Direction
Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported

Units: G Recovered: .00

Oxygenate: Not reported